







TECHNICAL BULLETIN TECH-01-2020

### VW 2.0L - 836026-5005S TURBOCHARGER REPLACEMENT

6<sup>TH</sup> JANUARY 2021



Genreugangethaption.com MAY. 12, 22



## VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

#### Dear Customer,

Please note, that production of turbocharger 04L 253 014 L / 830323-5006S was stopped.

As a replacement is available turbocharger 04L 253 014 M / 873767-5001S, which <u>is not a direct service replacement</u> for 830323-5006S.

• There is a different position of the flange for EGR pipe on turbine housing – see below



#### To replace turbocharger 830323-5006S to be ordered following:

- o From Garrett Turbocharger 873767-5001S
- o From franchised VW dealer
  - EGR pipe
  - Gaskets
  - Heatshield
  - Necessary fasteners








Genreuganrethaption.com MAY. 12, 22



# VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

#### Parts to be ordered from franchised VW dealer

- o EGR pipe
- Gaskets
- Heatshield
- Necessary fasteners



Please distribute this information to all in your company who may need it.

Best Regards,
IAM Technical Specialist support team.
Garrett – Advancing Motion







Genreuganrethmotion.com MAY. 12, 22